

ref no MNK05 031

Ix-Xaghra I-Hamra,

Category Rural

Site Description (Address)

Corbelled Hut at Ix-Xaghra I-Hamra, Manikata

**Eastings** 4155

Manikata

**Northings** 7827

Period unknown

SS No1

SS No2

Description

4078

Small circular corbelled hut with a low entrance and a flat lintel. The door faces west and part of the right door jamb has partly collapsed as is part of the roof.

SS No4 SS No3

Date of survey sheet: 1992

#### **Present Utilisation**

Mone

### Comments

Needs consolidation and restoration





**Condition**Parlty collapsed

**Degree of Protection** None

**Proposed Protection**Grade 1

## **Basic Bibliography**

Fsadni, M., 1999, The Girna: The Maltese Corbelled Stone Hut, Malta, Dominican Publication.



ref no MNK05 032

Location Ix-Xatba, Manikata Category Rural

Site Description (Address) Field Room at Ix-Xatba, Manikata

**Eastings** 4134

**Northings** 7832

Period unknown

SS No1

SS No2

Description

4078

Very small sqaure field room with its entrance facing the east. The external skin of the wall is partly collapsed.

SS No4

SS No3

Date of survey sheet:

1992

#### **Present Utilisation**

None

#### Comments

Needs consolidation and restoration





**Condition**Partly collapsed

**Degree of Protection** None

**Proposed Protection**Grade 2

## **Basic Bibliography**

Jaccarini, C., 1998, Ir-Razzett: The Maltese Famhouse, Malta. P.E.G. Ltd.



ref no MNK05 033

Location

Ix-Xagħra tal-Qortin,

Category Rural **Site Description (Address)** 

Corbelled hut at Ix-Xagħra tal-Qortin, Manikata

Eastings 4061

Manikata

Northings 7817 **Period** unknown

SS No1

SS No2

4078

SS No4 SS No3

Date of survey sheet: 1992

Description


Square-plan corbelled hut with domed roof. The corbelled hut has been substantially altered with a field room built on its eastern wall. Its entrance lies to the south and has a niche above the flat

lintelled-doorway. This hut is inaccessable.

#### **Present Utilisation**

Field Room

#### Comments





**Condition**Well maintained

**Degree of Protection** None

**Proposed Protection**Grade 1

## **Basic Bibliography**

Fsadni, M., 1999, The Girna: The Maltese Corbelled Stone Hut, Malta, Dominican Publication.



ref no MNK05 034

Location lx-Xagħra tal-Qortin, Category Rock-Cut **Site Description (Address)** 

Rock-Cut Channel at Ix-Xaghra tal-Qortin, Manikata

Eastings 4056

Manikata

Northings 7804 **Period** unknown

SS No1

SS No2

Description

4078

Single rock-cut channel or cart rut running to a length of 0.80m with a width of 0.15m and a depth of 0.15m.

SS No4 SS No3


Date of survey sheet: 1992

#### **Present Utilisation**

None

#### Comments

It is not clear whether the channel was used for the drainage of water when the area was put to agricultural use, or if it is the surviving rut of a pair of cart ruts or whether it was linked to a military purpose.



## MNK05\_034



**Condition** Fair

**Degree of Protection** None

**Proposed Protection**Grade 3



ref no MNK05 035

Location lx-Xagħra tal-Qortin, Category Military **Site Description (Address)** 

ix-xagnra tai-Qort Manikata Military

Cement posts at Ix-Xagħra tal-Qortin, Manikata

Eastings 4050 Northings 7813 Period

British Period, 19th/20th century

**SS No1** 4078

SS No2

SS No3

Description

SS No4

4077

A number of equilateral cuboid pink cement posts with chamfered corners. They are 12m apart and run in a straight line from the remains of an open concrete guard post at the edge of the cliffs of

Rdum Majjiesa to Ix-Xaghra tal-Qortin.

1992


#### **Present Utilisation**

Date of survey sheet:

None

#### Comments

The area beyond the line created by these posts is derelict and the field walls have been abandoned or razed to the ground, possibly resulting from British military operations in the area.






**Condition**Good although a few of the posts are no longer in situ

**Degree of Protection** None

**Proposed Protection**Grade 2



MNK05\_035\_004





ref no MNK05\_036

Location lx-Xagħra tal-Qortin, Category Rock-Cut **Site Description (Address)** 

Rock-cut trench at Ix-Xaghra tal-Qortin, Manikata

Eastings 4052

Manikata

Northings 7797 Period

Possibly British

SS No1

SS No2

4077

SS No4 SS No3

Date of survey sheet: 1992

Description

Rock-cut trench measuring 1m by 3.35m. Its depth cannot be determined because it is filled with rubble and other litter. Although resembling a tomb shaft, it is propably British, since part of the ledge is dressed with concrete. Such a trench could have been linked to the British miltary operations in the area. However, one cannot exclude that is was dug in Classical times and reused later


on for a different purpose.

#### **Present Utilisation**


None

#### Comments

The trench needs to be cleared to determine its past use.



## MNK05\_036



**Condition** Bad **Degree of Protection** None

**Proposed Protection**Grade 2





ref no MNK05 037

Ix-Xagħra tal-Qortin,

Category Rock-Cut

**Site Description (Address)** 

Manikata

Quarry at Ix-Xaghra tal-Qortin, Manikata

**Eastings** 4053

**Northings** 7752

Period

Possibly Modern

SS No1

4077

SS No4

SS No2

SS No3

Date of survey sheet: 1992 **Description** 

A small quarry located on the road side, porobably used for the extraction of building material for the construction of structures and rubble walls in the vicinity. The quarry is of an irregular shape but its approximate diameter is 6.75m. A rubble wall was built on the

NW section of the quarry to support the country track.

#### **Present Utilisation**

Dump

#### Comments

The quarry needs to be cleared so as to reveal any tool marks, and hence a broad date range



## MNK05\_035\_002





**Condition** Bad **Degree of Protection** None

**Proposed Protection**Grade 3



ref no MNK05\_038

Ix-Xagħra tal-Qortin, Manikata

Category

Road

SS No2

SS No3

1992

**Site Description (Address)** 

Country track at Ix-Xaghra tal-Qortin, Manikata

**Eastings** 

**Northings** 4057 7770

Period

Early Modern

SS No1

4077

SS No4

**Description** 

A derelcit country track runnig for a length of approximately 160m. It is bordered by rubble walls that are still extant. The track leads

to what is now garrigue wasteland.

Date of survey sheet:

#### **Present Utilisation**

None

#### Comments

Probably this track came out of use when fields in this area were abandoned with the start of British military operation. The road surface is not visible due to the overgrown vegetation.





**Condition** Overgrown

**Degree of Protection** None

**Proposed Protection**Grade 2



ref no MNK05\_039

Location
II-Moxa ta' Għajn
Tuffieħa, Manikata

**Category** Rural **Site Description (Address)** 

Circular dry stone structure at II-Moxa ta' Għajn Tuffieħa, Manikata

Eastings 4052 Northings 7766

SS No2

**Period** unknown

SS No1

4077

SS No4 SS No3

Date of survey sheet: 1992

Description

A natural hollow of an irregular shape whose perimter has been surrounded by a continuous rubble wall. The wall is 0.80m thick and its diameter is of about 6m. The floor of this hollow is undressed and unworked rock. Since the wall is partially collapsed, the presence of an entrance cannot be determined. In close proximity to this structure there is evidence of rock cutting and relatively large depression in the rock. This is oval in shape and has an average diameter of 2m. A water channel has been dug on its southern face. There is a pottery scatter in the area.

#### **Present Utilisation**

None

#### Comments

The circular structure could be a destroyed corbelled hut that was abandoned with the building of farmhouse MNK05\_040.





**Condition** Bad **Degree of Protection** None

Proposed Protection
Grade 2



MNK05\_039\_003



ref no MNK05 040

Location
II-Moxa ta' Għajn
Tuffieħa, Manikata

**Category** Rural **Site Description (Address)** 

Famrhouse at II-Moxa ta' Għajn Tuffieħa, Manikata

**Eastings Northings** 4051 7763

Period unknown

SS No1

SS No2

4077

SS No4 SS No3

Date of survey sheet: 1992

Description

L-Shaped farmhouse consisting of a main building built on 2 floors and 5 outer buildings. Second floor, is reached by an external staricase. Outer building contains 3 mangers on the exterior façade and are separated into 4 chambers each with a distinct entrance and a manger on its western wall. Most of the roofs have collapsed but they have been built using kileb, xorok and wooden beams. All rooms were also closed. Ground floor of the main building has a blocked doorway in its northern wall. 5th room of the outer building, adjacent to main building has a separate entrance into the courtyard. Interior shows signs of plastering, white-washing and a number of niches, some of which have soot. On its SW corner there is a shelf with a cross graffito. External staircase has a small recess beneath it. Walls of main building have been white-washed, plastered and have a number of niches. The roof has collapsed. To the east of the courtyard are a number of collapsed dry stone structures. Courtyard has a bell-shaped cistern and signs of quarrying.

#### **Present Utilisation**

None

#### Comments

A well-dressed wall dating to the British period is found along its western wall.





**Condition**Bad; in need of reconstruction

**Degree of Protection** None

**Proposed Protection**Grade 2

